

# Service Bulletin

NO. 1233

February 1990

## Light Duty Transaxles

**Light Duty Input Shaft Change From .750 Dia. to 17mm Dia. . Effective Date August 1, 1990**

This Service Bulletin applies to Models 750, 770, 780 & 850 Series Transaxle Parts Information Manuals **6-412, 6-413, 6-416 & 6-417.**

Ref. No.	Part No.	Description	Qty.
1	104410 (old)	Cover Subassembly (used prior to date code 080190), used with 103768 .750 (19mm) dia. Shaft/Bearing Subassembly.	1
	106071 (new)	Cover Subassembly (used in date code 080190 & after), used with 106073 17mm dia. (.669) Shaft/Bearing Subassembly.	1
2	103768 (old)	Shaft/Bearing Subassembly, .750 dia., (19mm) used in 104410 Cover Subassembly (used prior to date code 080190)	1
	106073 (new)	Shaft/Bearing Subassembly, 17mm dia. (.669), used in 106071 Cover Subassembly (used in date code 080190 & after)	1
3	NSS	Bearing, (part of item #2)	1
4	NSS	Ring, Retaining External (part of item #2)	1
6	104538 (old)	Seal, Input Shaft (used prior to date code 080190), used with .750 dia. (19mm) Shaft	1
	93955 (new)	Seal, Input Shaft (used in date code 080190 & after), used with 17mm dia. (.669) Shaft	1

Eaton Corporation  
Hydraulics Division  
15151 Hwy. 5  
Eden Prairie, MN 55344  
Telephone 612/937-9800  
Fax 612/937-7130

Eaton Ltd.  
Hydraulics Division  
Glenrothes, Fife  
Scotland, KY7 4NW  
Telephone 01-592-771-771  
Fax 01-592-773-184

Eaton GmbH  
Hydraulics Products  
Am Schimmersfeld 7  
40880 Ratingen, Germany  
Telephone 02102-406-830  
Fax 02102-406-800



Quality System Certified  
Products in this catalog are manufactured  
in an ISO-9001-certified site.

---

**EAT•N**